

## Firmware Version 230802 Summary

**Purpose of Release:** This is the updated release of the firmware for the S2040 as a general maintenance release.

**Date:** Dec 11, 2023

### **Recommended Host Driver Version:**

S2000 Driver Installation Disk Version: 8.2

## **Firmware Update Process:**

With a S2000 scanner is connected and the drivers are installed on the host computer. Uses2000 230802 Firmware.exe to update the firmware

.

## **Embedded Firmware subsystems**

Name Versions

FPGA Version: 3A.0.0 (Original Main Board)

72.0.0 (Updated Main Board)

Platform Version: 230802

#### **New Features for Firmware 230802:**

1. None

#### **Improvements for Firmware 230802:**

- 1. SAGE-2684 Addressed root cause of error ID 0039 during normal operation
- 2. SAGE-2653 Fixed issue where scanner was not saving the time & date of first host connection.
- 3. SAGE-2507 Correct A3 flatbed pixel size to fix OCR issue.
- 4. SAGE-1747 Scanner will restart automatically without user intervention after firmware is updated

#### **Known Issues:**

1. None

### **Notes:**



## Firmware Version 210503 Summary

**Purpose of Release:** This is the updated release of the firmware for the S2040 as a general maintenance release.

**Date:** May 26, 2021

#### **Recommended Host Driver Version:**

S2000 Driver Installation Disk Version: 8.2

## **Firmware Update Process:**

With a S2000 scanner is connected and the drivers are installed on the host computer.

Uses2000\_210503\_40\_Frimware.exe to update the firmware

**Embedded Firmware subsystems** 

Name Versions

FPGA Version: 3A.0.0 (Original Main Board)

72.0.0 (Updated Main Board)

Platform Version: 210503

#### **New Features for Firmware 210503:**

2. None

### **Improvements for Firmware 210503:**

- 5. SAGE-742 Fixed Documents not cropped properly when multiple document cropping is enabled when scanning with Legal Size Flatbed.
- 6. SAGE-1247 Fixed Edge Fill with tears on a Dog-Ear Corner leaving a bar image artifacts
- 7. SAGE-1296 Fixed Image Processing Failed with Blank Page deletion and carrier sheet folded document is used
- 8. SAGE-1309 Fixed Multifeed set to Stop Scanning and Jam set to Pause scanning can result in Critical Error
- 9. SAGE-1369 Fixed Sheet counter is not incrementing when scans are performed from the Passport Flatbed scanner.
- 10. SAGE-1428 Fixed Mechanical Calibration Fails but SVT UI message reports Pass
- 11. SAGE-1531 Fixed A3 flatbed camera travel distance is off by a factor of 2 resulting in maximum document length setting in the driver not being used correctly.
- 12. SAGE-1582 Changed: Disable Arabic for Auto Page Orientation (AO) in all S2000 Default configuration, Arabic AO can sometime improperly auto rotate handwritten documents in Latin based languages. If Arabic language AO is required, contact Kodak Alaris service and support
- 13. SAGE-1711 Fixed Critical Errors caused when a Jam occurs with Cropping Mode set to Aggressive Cropping
- 14. SAGE-2201 Fixed A blank images intermittently occurs when using ECDO with Auto Color Detect..
- 15. SAGE-2250 Fixed Binarization Interior Edge Artifact When Image Edge Fill FIXED "White" is Selected
- 16. SAGE-2257 Fixed OCP Firmware sometimes crashed when saving logs

### **Known Issues:**

2. SAGE-508 - When using Multiple Document Locate with Sleeve scanning that is the documents are placed in the sleeve such that two documents are in the same horizontal plane in the sleeve that the front and rear images may not be matched properly. The workaround is to place the documents such that they are not in the same horizontal plane in the sleeve.



- 3. SAGE-764 A4/Legal Flatbed with Multiple Document Locate. Depending on the how the document is placed relative to Skew to the platen camera some boarder may be left around the resulting images
- 4. SAGE-766 A4/Legal Flatbed auto cropping with dark green documents at 600 DPI can leave black boarders on the image.

#### **Notes:**



## Firmware Version 210201 Summary

**Purpose of Release:** This is the updated release of the firmware for the S2040 to support the original and a new hardware (Main Board) configuration.

Date: February 3, 2021

#### **Recommended Host Driver Version:**

S2000 Driver Installation Disk Version: 7.8

### **Firmware Update Process:**

With a S2000 scanner is connected and the drivers are installed on the host computer.

Use <u>\$2000\_210201\_40\_Frimware.exe</u> to update the firmware

**Embedded Firmware subsystems** 

Name Versions

\* FPGA Version: 3A.0.0 (Original Main Board)

72.0.0 (Updated Main Board)

\* Platform Version: 210201

#### **New Features for Firmware 210201:**

- 3. Czech language support added to the OCP
- 4. Support both original and updated hardware configurations
  - a. There are no functional differences between the hardware configuration changes and V210301 supports both configurations.

## **Improvements for Firmware 210201:**

17. none

#### **Known Issues:**

- 5. SAGE-508 When using Multiple Document Locate with Sleeve scanning that is the documents are placed in the sleeve such that two documents are in the same horizontal plane in the sleeve that the front and rear images may not be matched properly. The workaround is to place the documents such that they are not in the same horizontal plane in the sleeve.
- 6. SAGE-764 A4/Legal Flatbed with Multiple Document Locate. Depending on the how the document is placed relative to Skew to the platen camera some boarder may be left around the resulting images
- 7. SAGE-766 A4/Legal Flatbed auto cropping with dark green documents at 600 DPI can leave black boarders on the image.

#### Notes:



## Firmware Version 200502 Summary

**Purpose of Release:** This is the updated release of the firmware for the S2040

**Date:** May 6, 2020

### **Recommended Host Driver Version:**

S2000 Driver Installation Disk Version: 5.3

#### **Firmware Update Process:**

With a S2000 scanner is connected and the drivers are installed on the host computer. Use s2000 200502 40 Frimware.exe to update the firmware

.

## **Embedded Firmware subsystems**

Name	Versions
* FPGA Version:	19.0.0

\* IPC Version: 200502 Release (IpcApp)

\* SMC Version: 00000b SMC Dev Feb 13 2020 12:18:36

\* SPC Version: 190201 Release (Spc0)

\* DSP Version: 06072400

\* DSP Build: 5cb7a608

\* Front Scan Module Version: 00000000

\* Rear Scan Module Version: 00000000

\* Platform Version: 200502

\* Firmware UID: 63cf5e63bfca24fe35de50a812218606

#### New Features for Firmware 200502:

- 1. Updates for Branding change from Alaris to Kodak
  - a. Splash screen graphic
  - b. Ready screen graphic
  - c. USB Product descriptor changed to KODAK S20X0 scanners

## **Improvements for Firmware 200502:**

1. none

#### **Known Issues:**

- 1. SAGE-508 When using Multiple Document Locate with Sleeve scanning that is the documents are placed in the sleeve such that two documents are in the same horizontal plane in the sleeve that the front and rear images may not be matched properly. The workaround is to place the documents such that they are not in the same horizontal plane in the sleeve.
- 2. SAGE-764 A4/Legal Flatbed with Multiple Document Locate. Depending on the how the document is placed relative to Skew to the platen camera some boarder may be left around the resulting images
- 3. SAGE-766 A4/Legal Flatbed auto cropping with dark green documents at 600 DPI can leave black boarders on the image.

#### **Notes:**



## Firmware Version 190405 Summary

**Purpose of Release:** This is the updated release of the firmware for the S2040

**Date:** June 5, 2019

### **Recommended Host Driver Version:**

S2000 Driver Installation Disk Version: 2.06

#### **Firmware Update Process:**

With a S2000 scanner is connected and the drivers are installed on the host computer. Use s2000 190405 40 Installer.exe to update the firmware

## **Embedded Firmware subsystems**

Name	Versions
* FPGA Version:	3a.0.0
* IPC Version:	190404 Release (IpcApp)
* SMC Version:	00000c SMC Dev
* SPC Version:	190201 Release (Spc0)
* 505 1/	

\* DSP Version: 06072400 \* DSP Build: 5cb7a608 \* Front Scan Module Version: 00000000 \* Rear Scan Module Version: 00000000 \* Platform Version: 190405

\* Firmware UID: ef03a269b1b15dd19ddc694e77424d3d

#### **New Features from Firmware 181201:**

1. None

## **Improvements from Firmware 181201:**

1. SAGE-1331 – Decrease time from scan begin to first paper movement. (Approximately 1.2 seconds)

### **Known Issues:**

- 1. SAGE-508 When using Multiple Document Locate with Sleeve scanning that is the documents are placed in the sleeve such that two documents are in the same horizontal plane in the sleeve that the front and rear images may not be matched properly. The workaround is to place the documents such that they are not in the same horizontal plane in the sleeve.
- 2. SAGE-764 A4/Legal Flatbed with Multiple Document Locate. Depending on the how the document is placed relative to Skew to the platen camera some boarder may be left around the resulting images
- 3. SAGE-766 A4/Legal Flatbed auto cropping with dark green documents at 600 DPI can leave black boarders on the image.

#### Notes:



## Firmware Version 181201 Summary

**Purpose of Release:** This is the updated release of the firmware for the S2040

Date: December 6, 2018

#### **Recommended Host Driver Version:**

S2000 Driver Installation Disk Version: 2.06

#### **Firmware Update Process:**

With a S2000 scanner is connected and the drivers are installed on the host computer.

Use <u>\$2000\_181201\_40\_Installer.exe</u> to update the firmware

### **Embedded Firmware subsystems**

**Name Versions** \* FPGA Version: 19.0.0

\* IPC Version: 181201 Release (IpcApp)

\* SMC Version: 00000b SMC Dev Jun 28 2018 17:26:48

\* SPC Version: 180601 Release (Spc0)

\* Firmware UID: 63cf5e63bfca24fe35de50a812218606

#### **New Features from Firmware 181005:**

1. None

### **Improvements from Firmware 181005:**

1. SAGE-1248 - OCP shows portion of scroll bar control on screen

#### **Known Issues:**

- 1. SAGE-508 When using Multiple Document Locate with Sleeve scanning that is the documents are placed in the sleeve such that two documents are in the same horizontal plane in the sleeve that the front and rear images may not be matched properly. The workaround is to place the documents such that they are not in the same horizontal plane in the sleeve.
- 2. SAGE-764 A4/Legal Flatbed with Multiple Document Locate. Depending on the how the document is placed relative to Skew to the platen camera some boarder may be left around the resulting images
- 3. SAGE-766 A4/Legal Flatbed auto cropping with dark green documents at 600 DPI can leave black boarders on the image.

#### Notes:



## Firmware Version 181005 Summary

**Purpose of Release:** This is the updated release of the firmware for the S2040

**Date:** October 18, 2018

#### **Recommended Host Driver Version:**

S2000 Driver Installation Disk Version: 2.06

#### **Firmware Update Process:**

With a S2000 scanner is connected and the drivers are installed on the host computer.

Use <u>\$2000\_181005\_40\_Installer.exe</u> to update the firmware

#### **Embedded Firmware subsystems**

Name Versions \* FPGA Version: 19.0.0

\* IPC Version: 181004 Release (IpcApp)

\* SMC Version: 00000b SMC Dev Jun 28 2018 17:26:48

\* SPC Version: 180601 Release (Spc0)

\* DSP Version: 06072000

\* DSP Build: 5bc682f7

\* Front Scan Module Version: 00000000

\* Rear Scan Module Version: 00000000

\* Platform Version: 181005

\* Firmware UID: 63cf5e63bfca24fe35de50a812218606

#### **New Features from Firmware 180701:**

- 1. Support for Passport Flatbed Catalog number 1029792
- 2. Decrease total scan and image processing time when using flatbeds

## **Improvements from Firmware 180701:**

1. SAGE-908 - Barcode read changes so that a barcode read on i2820 is also read on S2000w.

## **Known Issues:**

- 1. SAGE-508 When using Multiple Document Locate with Sleeve scanning that is the documents are placed in the sleeve such that two documents are in the same horizontal plane in the sleeve that the front and rear images may not be matched properly. The workaround is to place the documents such that they are not in the same horizontal plane in the sleeve.
- 2. SAGE-764 A4/Legal Flatbed with Multiple Document Locate. Depending on the how the document is placed relative to Skew to the platen camera some boarder may be left around the resulting images
- 3. SAGE-766 A4/Legal Flatbed auto cropping with dark green documents at 600 DPI can leave black boarders on the image.

#### **Notes:**



## Firmware Version 180701 Summary

**Purpose of Release:** This is the initial release of firmware for the S2040.

**Date:** July 11, 2018

#### **Recommended Host Driver Version:**

S2000 Driver Installation Disk Version: 02.06.00

## **Embedded Firmware subsystems**

Name	Versions
* FPGA Version:	3a.0.0

\* IPC Version: 180504 Release (IpcApp)

\* SMC Version: 00000c SMC Dev Jul 6 2018 13:31:10

\* SPC Version: 180502 Release (Spc1)

\* DSP Version: 06071100

\* DSP Build: 5aea0951

\* Front Scan Module Version: 00000000

\* Rear Scan Module Version: 00000000

\* Platform Version: 180701

\* Firmware UID: ef03a269b1b15dd19ddc694e77424d3d

## **Firmware Update Process:**

With a S2040 scanner is connected and the drivers are installed on the host computer. Use s2000\_180601\_40\_Installer.exe to update the firmware

#### **New Features from Firmware xx.xx.xx:**

1. initial release of firmware

## Improvements from FW xx.xx.xx:

1. initial release of firmware

## **Known Issues:**

1. none

#### **Notes:**