# Kodak Trūper 3210-3610 Series Scanners Firmware Release Notes

# InstallFW\_Truper3210-3610\_v01.10.00 Summary

Purpose of Release: Support updated electronics changes needed to support new power usage requirements. In December of 2012 Kodak updated three boards in the Trüper series scanners to add more adjustment to the multifeed detection and for Energy Star standards updates. The scanner firmware and Service Utility were updated to support this change. Note that these changes are not visible in the general User Software or general operation of the scanner. The Kodak Service Utility version 1.1 was updated to enable the new adjustments to the scanner Ultrasonic sensors.

NOTE: Unless there is a need for Kodak Service to adjust the Multifeed settings this firmware update is not needed for scanner manufactured before December 2012. This setting is not accessible without assistance from Kodak Service.

Date: June 2014

#### **Supported Models:**

Kodak Branded Trūper 3210 and 3610

#### Versions:

Firmware: v1.10.0			
🚺 KODAK User Utility			
Scanner Status:			
Scanner has no error.			
	Scanner Information		
		KODAK 3610	
	Firmware Version:	1.10	
	Front Memory:	576 MB	
	Back Memory:	528 MB	
	Interface:	STI USB (2.0)	
	Pre-Imprinter:	Enable	

## New Features from previous version (v1.1):

1. Add a broader range of adjustment for the scanners Multifeed Detection system through the Service Utility v1.1

## **Improvements from previous version (v1.1):**

1. Support changes in the Controller board, Driver board and Power board