

# Kodak Sidekick 1400u Scanner Software Release Notes

## **InstallSoftware\_Sidekick\_1400u\_v1.3\_VRS4.50 (5K0241V1.3) Summary**

**Purpose of Release:** This release corrects an installation issue with the TWAIN driver only.

(Note: The same installation CD is currently used for both the Kodak branded Sidekick 1400u and Trüper 3210/3610 Scanners)

**Date:** November, 17<sup>th</sup> 2011

**Supported Models:**

Kodak Branded Sidekick 1400u

Kodak Branded Trüper 3210 and 3610

**Supported Firmware Versions:**

Kodak Branded Sidekick Firmware 1.0

Kodak Branded Trüper Firmware 1.0

Kodak Branded Trüper Firmware 1.1 (recommended)

**Versions:**

VRS: 4.50.032.260

Kodak NOU (Operator Utility) 1.0.0.0

ISIS/Twain driver(Trüper): 1.2.11104.11002

ISIS/Twain driver(Sidekick): 1.1.11104.11001

**New Features from previous version (v1.2):**

1. (none)

**Improvements from previous version (1.2):**

1. Corrected an installation issue with the Trüper TWAIN driver that did not install all of the required run time components.


## InstallSoftware\_Sidekick1400u\_v1.2\_VRS4.50 (7J4079V1.2) Summary

**Purpose of Release:** This was the second release of the install CD for the Kodak Branded Sidekick 1400u scanner. The ISIS and TWAIN drivers on this CD will only connect to Kodak Branded Trüper or Sidekick Scanners. (Note: The same installation CD is currently used for both the Kodak branded Sidekick 1400u and Trüper 3210/3610 Scanners)

**Date:** December, 10<sup>th</sup> 2010

### Supported Models:

This software/driver release will only support Kodak Trüper or Sidekick scanners that report to the host PC in Windows Device Manager as “Kodak...” devices. If your scanner reports in Device Manager as a “BBH...” device then you must use a CD with a letter version (ie RevG) or upgrade your scanners firmware to the Kodak firmware version 1.0 or higher. The software and drivers on this CD (v1.2) must only be used for “Kodak Branded” Trüper or Sidekick Scanners.



### Supported Firmware Versions:

- Kodak Branded Sidekick Firmware 1.0
- Kodak Branded Trüper Firmware 1.0
- Kodak Branded Trüper Firmware 1.1 (recommended)

### Supported Operating Systems:

- Trüper and Sidekick
  - WINDOWS XP Pro (32bit only)
  - WINDOWS Vista (32 bit)
  - WINDOWS 7 (32bit)
- Trüper only
  - WINDOWS Vista (64bit USB only)
  - WINDOWS 7 (64bit USB only)

### Versions:

VRS:	4.50.032.260
Kodak NOU (Operator Utility)	1.0
ISIS/Twain driver(Trüper):	1.2.11010.14001
ISIS/Twain driver(Sidekick):	1.1.11008.5001

### New Features from previous version (Rev G):

1. Support for Kodak Branded Scanners.

### Improvements from previous version (Rev G):

2. (none)

## **InstallSoftware\_Sidekick1400u\_v1.0\_VRS4.50 (7J4079) Summary**

**Purpose of Release:** This release was shipped with the first Kodak Branded Trüper scanners. This CD is identical to the version 1.2 with the exception of some non-English translation updates for the Installation program and the User Utility.

The Kodak Trüper and Sidekick CD 1.0 do not support BBH branded scanners.

**Date:** 2010

### **Supported Models and Versions:**

(see CD 1.2)

### **New Features from previous version (Rev B):**

1. Support for Kodak Branded Scanners.

### **Improvements from previous version (Rev B):**

2. (none)

## **InstallSoftware\_Sidekick\_RevG\_VRS4.20 Summary**

**Purpose of Release:** This was the last release of the install CD (Sidekick Install S005523 Rev G OEM VRS v4.20.032). This CD can be used for a new install of the BBH/Kodak 1200 or 1400 or 1400u scanner. This driver install CD was created as a Bowe Bell and Howell Scanner product.

**Date:** 2009

**Supported Models:** This software/driver release will only support Trüper scanners that report to the host PC in Windows Device Manager as “BBH...” devices.

### **Versions:**

VRS:	4.20.039
ISIS/TWAIN driver:	1.1.10703.19001