

# **Kodak Trüper 3210-3610 Series Scanners** **Software Release Notes**

## **InstallSoftware\_Trüper3210-3610\_v1.6 Summary**

**Purpose of Release:** This release includes an update to Kodak OEM VRS 5.1 Professional to support Windows 8.

*(Note: The drivers included on this CD cannot be used to install a BBH branded Trüper scanner.)*

**Date:** June 2014

### **Supported Models:**

Kodak Branded Trüper 3210 and 3610

### **Supported Firmware Versions:**

Kodak Branded Trüper Firmware 1.0 (not recommended)

Kodak Branded Trüper Firmware 1.1

Kodak Branded Trüper Firmware 1.10

### **Versions:**

VRS:	v5.1.474 Kodak
Kodak Operator Utility	1.2.0.0
ISIS/Twain driver:	1.2.11208.13001

### **New Features from previous version (v1.4):**

1. Kodak OEM VRS 5.1 Professional
2. Windows 8 support.

### **Improvements from previous version (v1.4):**

1. ISIS-PR#20494 TAG\_LASTPAGE\_ENDORSER is being double incremented when scanning in Duplex.
2. ISIS-PR#20486 (Trüper 3210 only) AutoSelect option is not available for selection when running in a Kofax Environment.

## InstallSoftware\_Trüper3210-3610\_v1.4 Summary

**Purpose of Release:** This release includes an update to Kodak OEM VRS 5.0 Professional. No other updates are included in this release.

*(Note: The drivers included on this CD cannot be used to install a BBH branded Trüper scanner.)*

VRS 5.0 Professional includes the new “Fluent” user interface, the Kofax Source Manager and VCDemo have been replaced with the VRS Admin Console and VRS Test Console (similar to the Kofax Elite VRS version). If you are not familiar with VRS Elite it is recommended that you review the VRS Installation Guide in the VRS folder on the downloaded installation CD and use the online help available in the VRS Admin Console and VRS Interactive Viewer following installation.

In General Kodak OEM VRS 5.0 Professional is identical to VRS Elite with the exception of the following VRS Elite only features.

- o Edge Fill
- o Merge Sides
- o Intelligent Halftone
- o Auto Profile
- o Device Health - Local
- o Device Health - SNMP Support

Upgrades from VRS 5 to VRS Elite are available for purchase from Kofax.

**Date:** January 2012

### **Supported Models:**

Kodak Branded Trüper 3210 and 3610

### **Supported Firmware Versions:**

Kodak Branded Trüper Firmware 1.0

Kodak Branded Trüper Firmware 1.1 (recommended)

### **Versions:**

VRS:	5.00.933 Kodak
Kodak Operator Utility	1.0.0.0
ISIS/Twain driver(Trüper):	1.2.11104.11002

### **New Features from previous version (v1.3):**

1. Kodak OEM VRS 5.0 Professional

### **Improvements from previous version (v1.3):**

1. (None)

## InstallSoftware\_Trüper3210-3610\_v1.2\_VRS4.50 (7J4079V1.2) Summary

**Purpose of Release:** This was the second release of the install CD for the Kodak Branded Trüper 3210 and 3610 scanners. The ISIS and TWAIN drivers on this CD will only connect to Kodak Branded Trüper or Sidekick Scanners. (Note: The same installation CD is currently used for both the Kodak branded Sidekick 1400u and Trüper 3210/3610 Scanners)

**Date:** December, 10<sup>th</sup> 2010 (update for Sidekick Windows 7 64bit support on 05/12/2011)

### Supported Models:

This software/driver release will only support Kodak Trüper or Sidekick scanners that report to the host PC in Windows Device Manager as “Kodak...” devices. If your scanner reports in Device Manager as a “BBH...” device then you must use a CD with a letter version (ie RevA) or upgrade your scanners firmware to the Kodak firmware version 1.0 or higher. The software and drivers on this CD (v1.2) must only be used for “Kodak Branded” Trüper or Sidekick Scanners.



### Supported Firmware Versions:

- Kodak Branded Sidekick Firmware 1.0
- Kodak Branded Trüper Firmware 1.0
- Kodak Branded Trüper Firmware 1.1 (recommended)

### Supported Operating Systems:

- Trüper and Sidekick
  - WINDOWS XP Pro (32bit only)
  - WINDOWS Vista (32 bit)
  - WINDOWS 7 (32bit and 64bit)

### Versions:

VRS:	4.50.032.260
Kodak Operator Utility	1.0
ISIS/Twain driver(Trüper):	1.2.11010.14001
ISIS/Twain driver(Sidekick):	1.1.11008.5001

### New Features from previous version (Rev B):

1. Support for Kodak Branded Scanners.

### Improvements from previous version (Rev B):

1. (none)

## **InstallSoftware\_Trüper3210-3610\_v1.0\_VRS4.50 (7J4079) Summary**

**Purpose of Release:** This release was shipped with the first Kodak Branded Trüper scanners. This CD is identical to the version 1.2 with the exception of some non-English translation updates for the Installation program and the User Utility.

The Kodak Trüper and Sidekick CD 1.0 do not support BBH branded scanners.

**Date:** 2010

### **Supported Models and Versions:**

(see CD 1.2)

### **New Features from previous version (Rev B):**

1. Support for Kodak Branded Scanners.

### **Improvements from previous version (Rev B):**

1. (none)

## InstallSoftware\_Trüper3210-3610\_RevB\_VRS4.50 Summary

**Purpose of Release:** This is the CD was shipped with BBH branded Trüper scanners in 2010. This CD was identical to the REV A CD with the exception of updated documentation that was rewritten and updated with the Kodak standards.

**Date:** mid 2010

**Supported Models:** This software/driver release will only support Trüper scanners that report to the host PC in Windows Device Manager as “BBH...” devices.



### Versions:

VRS: 4.50.032.157(b)  
ISIS/TWAIN driver: 1.2.10907.28002

### New Features from previous version (Rev A):

1. (none)

### Improvements from previous version (Rev A):


2. Improved User Documentation

## InstallSoftware\_Trüper3210-3610\_RevA\_VRS4.50 Summary

**Purpose of Release:** This is the first release of the install CD (Trüper Install S00???? Rev E OEM VRS v4.50.032). This CD can be used for a new install of the BBH/Kodak 3210 or 3610 scanner. This CD cannot be used to install a BBH/Kodak Trüper 3200 or Trüper 3600.

**Date:** March 2010

**Supported Models:** This software/driver release will only support Trüper scanners that report to the host PC in Windows Device Manager as “BBH...” devices.



### Versions:

VRS: 4.50.032.157(b)  
ISIS/TWAIN driver: 1.2.10907.28002