

Kodak i1100 Series Scanners Windows Drivers Release Notes

Software Version 1.07 Summary

Purpose of Release: This is a general release to the drivers' CD for the Kodak i1150WN and i1190WN scanners which remove SmartTouch and Capture Pro LE from the installation media and changes to a internet download for SmartTouch

Instructions for installing drivers using the ISO file:

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount)

For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3rd party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

Date:	September 13, 2017
CD Version:	1.07
Twain:	14.11
Driver:	1.8
Twaingui:	8.1
Hippo.dll:	52.30
KAScannerService:	1.6
Device.dll:	7.1
DeviceManager.dll:	1.4
ISIS driver:	1.1.11604.13001
Smart Touch App	no longer on CD
Capture Pro LE:	no longer on CD

Change Requests Implemented:

1. DIAS-1225 –Remove SmartTouch from installation media
2. DIAS-1226 – Remove Capture Pro LE from installation media
3. DIAS-1284 – Update Installer with link to Smart Touch and Capture Pro LE internet downloadable files.

Issues Fixed:

1. DIAS-1126-Address issue with Windows VM using USB Redirection

Known Issues:

None

Kodak i1100 Series Scanners Windows Drivers Release Notes

Software Version 1.06 Summary

Purpose of Release: This is a general release to the drivers for the Kodak i1150WN and i1190WN scanners which

Date:	January 26, 2017
CD Version:	1.06
Twain:	14.11
Driver:	1.8
Twaingui:	8.1
Hippo.dll:	52.30
KAScannerService:	1.6
Device.dll:	7.1
DeviceManager.dll:	1.4
ISIS driver:	1.1.11604.13001
Smart Touch App	1.8.70.478
Capture Pro LE:	5.2.1.13012

New Driver Features:

None

Issues Fixed:

DIAS-866 - Unable to communicate with scanner after PC comes out of Sleep Mode

DIAS-379 - Web installer is checking for the scanner to be connected

DIAS-390 - Scanner won't connect when on a different subnet

DIAS-375 - Turkish - TWAIN UI Title bar has ??? instead of scanner model

DIAS-363 - Both the German and French user manuals are missing the important information about installing on Win 8.1 and Server 2012

DIAS-941 - Include the Capture LE SW 5.2.1.13012

Known Issues:

None

Firmware Version 1.09 Summary

Purpose of Release: This is a CPE release for the Firmware.

Date:	December 21, 2016
WN Board Firmware:	1.09
Scanner Firmware:	1.32

Kodak i1100 Series Scanners Windows Drivers Release Notes

New/Changed Features:

1. DIAS-349 - Turn off Hole Fill in IP with Mobile app
2. DIAS-925 - Change Max Document length when scanning with Mobile app from 12 inches to 14 inches

Issues Fixed:

1. DIAS-644 - Special character, (**@ #**) **&** - _ ~ " " " ,can now be used in the network passwords.

Known Issues:

None

Kodak i1100 Series Scanners Windows Drivers Release Notes

Software Version 1.04 Summary

Purpose of Release: This is a general release to the drivers for the Kodak i1150WN and i1190WN scanners which allows the service diagnostic keys for Scan Validation Tool to continue to function after October 12, 2016. No other changes from DVD 1.03 are included.

Date:	October 12, 2016
Software	1.04

Firmware Version 1.06 Summary

Purpose of Release: This is a CPE release for the Firmware.

Date:	September 2, 2016
Firmware	1.06

New Features:

3. None

Issues Fixed:

2. Cannot connect to the router with apostrophe in SSID
3. Cannot save your configuration to scanner if the EasySetup description is blank

Known Issues:

None