

Kodak i5000 Series Scanners Firmware Release Notes **(For the i5200V and i5600V)**

Version 4.1.7 Summary

Purpose of Release: This firmware adds several requested new features and contains several bug fixes for the Kodak i5000 scanners. This firmware has been approved for production use for all customers.

Date: April 17th, 2015

Recommended Host Driver Version:

i5000V Driver Installation Disk Version: 1.4 or 1.5

New Features from 4.1.7

1. FW 4.4.2 - CR4756: Added support for a new disable print Application Override from the scanners operator control panel.
2. FW 4.3.0: Kodak i5x00 and i5x50 scanners now require unique firmware installers.
3. FW 4.2.0 - CR#4716: Added custom stop after patch feature via alteration.
4. FW 4.2.0: Added diagnostic support for Intelligent Document Protection sensors.

Improvements from 4.1.7:

1. FW 4.4.2 - CR#4744: Made the Control Panel User Counter accurately reflect images scanned by not increment on a non-Accepted Multifeed.

Supported Models:

Kodak i5200, Kodak i5600, Kodak i5800
Kodak i5200V, Kodak i5600V

Notes:

- This firmware can be used on all Kodak i5200/i5200V/i5600/i5600V/i5800 models but these release notes only cover this items that pertain to the Kodak i5000V scanners. For full release notes refer to the firmware download area of a Kodak i5000 model.
- If installing the firmware on Windows 7 PC a “Program Compatibility Assistant” message may be displayed. This is normal. Click “This Program installed correctly” to continue.

NOTE: With the firmware 4.3.0 and higher installed the Kodak i5000 scanners will have separate installer packages for the i5x00 and i5x50 models. The firmware installer file will now have “00” in the file name to denote that it will install on an i5x00 scanner

(i5200/i5200v/i5600/i5600v/i5800) or it will have a “50” in the file name to denote that it will install on an i5x50 scanner (i5850). If a Kodak i5850 scanner is updated to firmware 4.3.0 or higher the firmware installer must have a “50” (DownloadFirmware_i5000_50_Series_v0x.xx.xx.exe) in the name or it will not install.

Which firmware file do you need?

- i5200/i5600/i5800: DownloadFirmware_i5000_00_Series_v0x.xx.xx.exe
- i5200V/i5600V: DownloadFirmware_i5000_00_Series_v0x.xx.xx.exe
- i5850 with firmware version 4.2.00 or less: DownloadFirmware_i5000_00_Series_v0x.xx.xx.exe
- i5850 with firmware version 4.3.00 or greater: DownloadFirmware_i5000_50_Series_v0x.xx.xx.exe

(If in doubt you can try both... only one will work and no harm will be done.)

Kodak i5000 Series Scanners Firmware Release Notes **(For the i5200V and i5600V)**

Version 4.1.7 Summary

Purpose of Release: This firmware is a general release for all Kodak i5000 Series scanners. This firmware contains several bug fixes for the Kodak i5000 series scanners.

Date: November 11th, 2014

Recommended Host Driver Version:

i5000V Driver Installation Disk Version: 1.4 or 1.5

New Features from 3.14.5

1. None.

Improvements from 3.14.5:

1. FW 4.1.7 - PR# 24318: Corrected issue with i5000 Series Scanners failing Image Calibration due to LED parts variation.
2. PR#23511: Added an alteration option to override the Elevator position set by the host software.
3. Eliminated Fan noise when scanner is idle.

Supported Models:

Kodak i5200, Kodak i5600, Kodak i5800
Kodak i5200V, Kodak i5600V

Notes:

- This firmware can be used on all Kodak i5200/i5200V/i5600/i5600V/i5800 models but these release notes only cover this items that pertain to the Kodak i5000V scanners. For full release notes refer to the firmware download area of a Kodak i5000 model.
- If installing the firmware on Windows 7 PC a “Program Compatibility Assistant” message may be displayed. This is normal. Click “This Program installed correctly” to continue.

Kodak i5000 Series Scanners Firmware Release Notes **(For the i5200V and i5600V)**

Version 3.14.5 Summary

Purpose of Release: Support the VRS 5.1.0 update that is available in Driver CD 1.4.

Date: May 29th, 2014

New Features:

1. Added support for Windows 8. (Driver update required)

Improvements:

1. PR# 20512 FW: Corrected issue with i5000V scanners exiting first level of Energy Star mode by host initiated scan.

Supported Models:

Kodak i5200, Kodak i5600, Kodak i5800

Kodak i5200V, Kodak i5600V

Notes:

- This firmware can be used on all Kodak i5200/i5200V/i5600/i5600V/i5800 models but these release notes only cover this items that pertain to the Kodak i5000V scanners. For full release notes refer to the firmware download area of a Kodak i5000 model.
- If installing the firmware on Windows 7 PC a “Program Compatibility Assistant” message may be displayed. This is normal. Click “This Program installed correctly” to continue.

Kodak i5000 Series Scanners Firmware Release Notes **(For the i5200V and i5600V)**

Version 3.12.2 Summary

Purpose of Release: This is the first release of firmware intended for use with the Kodak i5200V and Kodak i5600V scanners.

Date: June 15, 2012

Supported Models:

Kodak i5200, Kodak i5600, Kodak i5800
Kodak i5200V, Kodak i5600V

Notes:

- For full release notes refer to the firmware download area of a Kodak i5000 model.