

# Kodak Ngenuity Series Scanners Software Release Notes

## **InstallSoftware\_Ngenuity\_RevC\_VRS4.50 Summary**

**Purpose of Release:** This was the third release of the install CD (Ngenuity Install S008830 Rev C OEM VRS v4.50.032.110 aka version 1.05a). This release does not update any VRS or direct drivers (TWAIN/ISIS). This CD has only updated install programs and user documentation.

There is no reason to upgrade a host PC that is running the RevB version drivers with this RevC CD. This version can be used to update a host PC running RevA level drivers.

**Date:** July, 2010

### **Supported Models:**

This software/driver release and all previous CD versions (RevA/RevB/RevC) will only support Ngenuity scanners that report to the host PC in Windows Device Manager as “BBH 9000...” devices. If your Ngenuity scanners reports in Device Manager as a “Kodak Ngenuity 9000...” device then these RevC drivers will not connect to the “Kodak Branded” Ngenuity Scanner.



### **Supported Firmware Versions:**

MC 1.10, 1.14  
CGA 3.20.024

### **Versions:**

VRS:	4.50.032.110
ISIS driver:	1.5.10912.4001
TWAIN:	1.20.0.0
NOU (Operator Utility)	1.02 April 9 <sup>th</sup> , 2009

### **New Features from previous version (Rev B):**

1. (none)

### **Improvements from previous version (Rev B):**

1. Updated User Manuals
2. Updated Setup.exe installer application

3.

## **InstallSoftware\_Ngenuity\_RevB\_VRS4.50 Summary**

**Purpose of Release:** This was the second release of the install CD (Ngenuity Install S008830 Rev B OEM VRS v4.50.032.110 aka version 1.05). This driver install CD was created as a Bowe Bell and Howell Scanner product.

**Date:** December, 2009

### **Supported Models:**

This software/driver release will only support Ngenuity scanners that report to the host PC in Windows Device Manager as “BBH 9000...” devices.



### **Versions:**

VRS:	4.50.032.110
ISIS driver:	1.5.10912.4001
TWAIN:	1.20.0.0
NOU (Operator Utility)	1.02 April 9 <sup>th</sup> , 2009

### **New Features from previous version (Rev A):**

1. OEM VRS 4.5 support.
2. Direct ISIS - TWAIN drivers with multistream capability and front /back printer control.
3. New **Ngenuity** Operator Utility (NOU) supports multiple languages.

### **Improvements from previous version (Rev A):**

- 1.

## Ngenuity Install S008830 Rev A OEM VRS v4.20 Summary

**Purpose of Release:** Initial Release (Version 1.0). This driver install CD was created as a Bowe Bell and Howell Scanner product.

**Date:** May, 2009

### Supported Models:

This software/driver release will only support Ngenuity scanners that report to the host PC in Windows Device Manager as “BBH 9000...” devices.



### Versions:

VRS:	4.20.032.411 BBH9000
ISIS driver:	(not on this CD)
TWAIN driver:	(not on this CD)
NOU (Operator Utility)	1.02 April 9 <sup>th</sup> , 2009