

Kodak i2000 Series Scanners Release Notes

Version CD 4.18 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Instructions for installing drivers using the ISO file:

For Windows 8.1 and 10 OS, mount the ISO file as a drive. (right click on the ISO file and select Mount)

For Windows 7 OS, either the ISO file has to be mounted as a drive or the ISO contents extracted to a folder using a 3rd party software tool. Software Tool providers (tools have not been tested and are not supported by the Kodak Alaris team, customers have reported that (7-zip, winrar, winiso) offer such capability.

Date:	September 11, 2017
CD Version:	4.18
Twain:	14.8
Driver.dll:	4.13
Twaingui:	8.6
Hippo.dll:	52.42
Device.dll:	5.6
DeviceManager.dll:	1.82
ISIS driver:	2.0.11508.25002
SmartTouch	No longer on CD
Flatbed4/bundle:	No longer bundled
Flatbed3/bundle	No longer bundled

Change Requests Implemented:

1. DIAS-1225 –Remove SmartTouch from installation media
2. DIAS-1226 –Remove Capture Pro LE from installation media
3. DIAS-1284 –Update Installer with link to Smart Touch and Capture Pro LE internet downloadable files.
4. DIAS-1136 –Many Changes to Automatic Rotation to support credit card scanning which are dark and have limited text printed on them
5. DIAS-1193 -Remove OmniPage/PaperPort from installation CD

Driver Issues Fixed:

1. DIAS-1198 Address a Citrix connectivity issue
2. DIAS-1126-Address issue with Windows VM using USB Redirection
- 3.

Kodak i2000 Series Scanners Release Notes

Known Issues:

1. None

Kodak i2000 Series Scanners Release Notes

Version CD 4.15 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	January 11, 2017
CD Version:	4.15
Smart Touch	1.8.67.448
Twain:	14.7
Driver.dll:	4.11
Twaingui:	8.1
Hippo.dll:	52.39
Device.dll:	5.5
DeviceManager.dll:	1.81
ISIS driver:	2.0.11508.25002
Flatbed4/bundle:	No longer bundled
Flatbed3/bundle	No longer bundled

New Driver Features:

1. Create a custom 2400 model for a specific customer in China

Smart Touch Features Fixed

1. None

Driver Issues Fixed:

4. None

Known Issues:

2. None

Kodak i2000 Series Scanners Release Notes

Version CD 4.14 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	December 14, 2016
CD Version:	4.14
Smart Touch	1.8.67.448
Twain:	14.7
Driver.dll:	4.11
Twaingui:	8.1
Hippo.dll:	52.39
Device.dll:	5.5
DeviceManager.dll:	1.80
ISIS driver:	2.0.11508.25002
Flatbed4/bundle:	No longer bundled
Flatbed3/bundle	No longer bundled

New Driver Features:

2. 64 Bit TWAIN Driver is available

Smart Touch Features Fixed

2. Smart Touch Configure Screen Strings missing intermittently
3. Folder permissions being changed when users are scanning
4. ST won't install when a folder redirection of the users' home directories on a server has been moved.
5. the date is being repeated in the filename string.

Driver Issues Fixed:

3. LCD Contrast Setting for i2x20 scanners is adjustable for FE Key
4. Linux Driver will run on computer with more than 19 cores
5. Unable to communicate with scanner after PC comes out of Sleep Mode
6. Various Manufacturing End of Line Process Issues

Known Issues:

None

Kodak i2000 Series Scanners Release Notes

Version CD 4.06.1 Summary

Purpose of Release: This is a general release to the drivers for the Kodak i2x20 scanners which allows the service diagnostics keys for Scan Validation Tool to continue to function after October 12, 2016. No other changes from DVD 4.06 are included

Date: October 12, 2016

CD Version: 4.06.01

Kodak i2000 Series Scanners Release Notes

Version CD 4.06 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	March 1st, 2016
CD Version:	4.06
Smart Touch	1.8.37.177
Twain:	14.4
Driver.dll:	4.7
Twaingui:	6.7
Hippo.dll:	52.35
Device.dll:	5.4
DeviceManager.dll:	1.74
ISIS driver:	2.0.11508.25002
Flatbed4/bundle:	No longer bundled
Flatbed3/bundle	No longer bundled

New Driver Features:

7. Add-support for "Orange and Red" color-dropout as a default option
8. Support Windows XP through 2016 (TWAIN only)
9. Remove ISIS XP support

Smart Touch Features Fixed

6. Scan to Word and Excel
7. Barcode
8. Scan to the cloud

Driver Issues Fixed:

1. ISIS ONLY: Receive "Unknown error. (-4523)" error message for White and Black fill color settings for Image Edge Fill with Color Photograph profile.

Known Issues:

None

Kodak i2000 Series Scanners Release Notes

Version CD 2.21 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	June 27th , 2014
CD Version:	2.21
Smart Touch	1.7.116
Twain:	12.12
Driver.dll:	2.15
Twaingui:	5.34
Hippo.dll:	52.17
Device.dll:	3.11
DeviceManager.dll:	1.66
ISIS driver:	2.0.11211.6001
Flatbed4/bundle:	2.17
Flatbed3/bundle	2.17

New Driver Features:

10. Fine tuned the algorithm used for content based blank page deletion
11. Reduced the size of the hole that hole fill uses
12. Changed the name of Blank Image Detection to Blank Image Deletion
13. Using the new Graphical Icons

Smart Touch Features Fixed

1. Replaced the OCR engine
2. Changed the URL used for BOX

Driver Issues Fixed:

1. Fixed the issue when changing the Max length of a document, it did not "stick"

Known Issues:

None

Kodak i2000 Series Scanners Release Notes

Version CD 2.15 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	October 11th, 2013
CD Version:	2.15
Smart Touch	1.7.85
Twain:	12.9
Driver.dll:	2.10
Twaingui:	5.19
Hippo.dll:	52.14
Device.dll:	3.8
DeviceManager.dll:	1.64
ISIS driver:	2.0.11211.6001
Flatbed4/bundle:	2.16
Flatbed3/bundle	2.16

New Driver Features:

None

Smart Touch Features Fixed

3. Corrected the issue when reviewing documents in the viewer, the scaling randomly changes
4. Updated the Attribution which was missing information on Win 7 64 bit OS

Driver Issues Fixed:

1. Fixed page-on-demand duplex scanning issue

Known Issues:

None

Kodak i2000 Series Scanners Release Notes

Version CD 2.11 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	June 26th, 2013
CD Version:	2.11
Twain:	12.8
Driver.dll:	2.8
Twaingui:	5.19
Hippo.dll:	52.14
Device.dll:	3.7
DeviceManager.dll:	1.56
ISIS driver:	2.0.11211.6001
Flatbed4/bundle:	2.11
Flatbed3/bundle	2.11

New Driver Features:

1. Added Arabic User's Guide to master CD
2. Attribution update for current dating

Smart Touch Features

None

Issues Fixed:

None

Known Issues:

None

Kodak i2000 Series Scanners Software Release Notes

Version CD 2.09 Summary

Purpose of Release: This is a CPE release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Kodak i2000 Series Scanners Release Notes

Date:	April 15th, 2013
CD Version:	2.09
Twain:	12.5
Driver.dll:	2.6
Twaingui:	5.6
Hippo.dll:	52.3
Device.dll:	3.5
DeviceManager.dll:	1.5
ISIS driver:	2.0.11211.6001
Flatbed4/bundle:	2.6
Flatbed3/bundle	2.6

New Driver Features:

3. New ISIS driver
4. Supports Ubuntu 12.04 LTS

Smart Touch Features

None

Issues Fixed:

1. New translated publications added to the CD

Known Issues:

None

Kodak i2000 Series Scanners Release Notes

Version CD 2.06 Summary

Purpose of Release: This is a CSM release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v2.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v2.xx.exe may be used to update a host PC that used an Install CD Version 1.xx for its first install.

Date:	November 30th, 2012
CD Version:	2.06
Twain:	12.5
Driver.dll:	2.6
Twaingui:	5.6
Hippo.dll:	52.3
Device.dll:	3.5
DeviceManager.dll:	1.5
ISIS driver:	2.0.11204.11001
Flatbed4/bundle:	2.6
Flatbed3/bundle:	2.6

New Driver Features:

1. Support for Windows 8 (32-bit and 64-bit)
2. Auto shutoff feature to meet EuP requirements

Smart Touch Features

1. Scan to the “Cloud” (Box.net, Evernote and other cloud apps using Webdev)
2. Silent installer option

Issues Fixed:

2. ECDO color names were not translated in Japanese
3. JPEG superior Quality level was 90, it is now 100
4. Smart Touch now launches Outlook 64-bit
5. Smart Touch – Files were named incorrectly when using dual stream output

Known Issues:

None

Kodak i2000 Series Scanners Release Notes

Version CD 1.17 Summary

Purpose of Release: This is a CSM release of drivers for the Kodak i2000 Series Scanners.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner) must be used. If the InstallSoftware_v1.xx.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v1.xx.exe may be used to update a host PC that used an Install CD Version 1.03 for its first install.

Date:	November 30th, 2011
CD Version:	1.17
Twain:	11.23
Driver.dll:	1.24
Twaingui:	4.42
Hippo.dll:	50.17.6.14
Device.dll:	1.21
DeviceManager.dll:	1.33
Flatbed4/bundle:	1.24
Flatbed3/bundle	1.16

New Driver Features:

3. Support for Kodak A3 Flatbed Scanners
4. Support for “hot pluggable” Flatbed Scanners
5. Support for 500 dpi scanning
6. The Const.ini file is back for language support
7. Greek, Polish and Romanian User’s Guides have been added
8. Improved the throughput when scanning short documents (i.e checks)

Smart Touch Features

3. Ability to enter a carriage return into the Smart Touch shortcut name
4. Improve the speed of the OCR output
5. Provide additional options for file name formats

Issues Fixed:

6. When using Capture Desktop and using another language other than English, the scanner can’t be found
7. Lexicon Executor crashing error
8. CAP_AUTOSCAN handling error
9. ISIS: Sheet Counter is not incrementing

Known Issues:

None

Kodak i2000 Series Scanners Release Notes

Version CD 1.5.3 Summary

Purpose of Release: Units are being built with either a Sony or Toshiba Camera. This version provides support for either camera.

Note: When installing a Kodak i2000 scanner on a host PC for the first time the Full Install CD (shipped with the scanner or downloaded from the Kodak Support Web site) must be used. If the InstallSoftware_v1.53.exe driver installer is used for a new installation the Kodak Smart Touch application will not be installed. The InstallSoftware_v1.5.3.exe may be used to update a host PC that used an Install CD Version 1.03 for its first install.

Date: October 12th, 2011

New Features:

Support for Sony cameras

Issues Fixed:

None

Known Issues: